



Dr. John Scheirs Litigation Experience 2002-Present

| Legal Firm | Nature of Job |
|--|--|
| Anderson Rice Lawyers , Level 10, 555 Lonsdale Street, Melbourne, VIC 3000. | Heat Seal Failures of Rice Bags |
| Australian Government Solicitor, HOBART TAS 7001 | Biodegradability of disposable nappies |
| Clayton Utz, 333 Collins Street, Melbourne VIC 3000 | Polypropylene Geomembrane failure |
| Clayton Utz, 333 Collins Street, Melbourne VIC 3000 | MDPE Gas pipe failure (squeeze off) |
| Corrs Chambers Westgarth, Bourke Place, 600 Bourke Street, Melbourne VIC 3000 | Biodegradability of PE-starch films |
| Crawford & Company (Aust) Pty Ltd The Tea House, Level 1, 28 Clarendon Street, Melbourne VIC | Failure analysis of crosslinked polyethylene water pipes |
| Crawford & Company (Aust) Pty Ltd The Tea House, Level 1, 28 Clarendon Street, Melbourne VIC | Failure analysis of Polyacetal Automotive Door Mechanism Plate |
| Crawford & Company (Aust) Pty Ltd The Tea House, Level 1, 28 Clarendon Street, Melbourne VIC | Failure Analysis and Investigation of Yogurt Tubes |
| Crawford & Company (Aust) Pty Ltd The Tea House, Level 1, 28 Clarendon Street, Melbourne VIC | Failure Analysis of PVC Water Filer Housing |
| Crawford & Company (Aust) Pty Ltd The Tea House, Level 1, 28 Clarendon Street, Melbourne VIC | Failure analysis of flat bread pouches |
| Crawford & Company (Aust) Pty Ltd The Tea House, Level 1, 28 Clarendon Street, Melbourne VIC | Failure analysis of barrier antipasto thermoformed trays |
| Crawford & Company (Aust) Pty Ltd The Tea House, Level 1, 28 Clarendon Street, Melbourne VIC | Failure analysis of leaking Indian curry sauce pouches |
| Crawford & Company (Aust) Pty Ltd The Tea House, Level 1, 28 Clarendon Street, Melbourne VIC | Analysis of failure of adhesive of foam underlay to wooden floor boards |
| Davies Collison Cave Solicitors Pty Ltd | Thermoformability of Plastic |

| | |
|--|---|
| 1 Nicholson Street , Melbourne VIC 3000 | |
| Deacons, Level 24, 385 Bourke Street, Melbourne VIC 3000 | Failure of fPP Grain Covers |
| Deacons, Level 24, 385 Bourke Street, Melbourne VIC 3000 | Failure of Cracked Nitrile Rubber Liner |
| Deacons Lawyers, Level 17, 175 Eagle Street, Brisbane QLD 4000 | Failure of PP-R water pipe |
| Ebsworth & Ebsworth, GPO Box 4542, Melbourne | Failure of Blow Moulded HDPE Pool Filters |
| UNSW Global Pty Limited | Failure of Plastic Exercise Balls |
| Freehills, Level 38, Central Plaza One, 345 Queen Street, Brisbane QLD 4000 | Failure of Jumping Castle Material |
| Freehills, 101 Collins St., Melbourne, VIC 3000, GPO Box 128A, Melbourne | Failure of Plastic Containers for Organic Liquid Peroxide |
| Gadens Lawyers, GPO Box 129, Brisbane 4001 | Failure of ASA Pool Fence |
| Gilshenan & Luton Lawyers Brisbane Queensland 4001 | Patent dispute involving bubble wrap insulation |
| Louis Gross & Associates, Barristers & Solicitors, Level 17, 390 St Kilda Road, Melbourne, VIC 3004 | Oxo-degradable Nappy Sacks |
| LegalIT Lawyer, Level 30, AMP Place, 10 Eagle Street, Brisbane, Qld 4001 | Perforated PVC film |
| Mallesons Stephen Jaques, Level 50, Bourke Place, 600 Bourke St., Melbourne VIC 3000 | Failure of Plastic Truck Air Intake |
| Mallesons Stephen Jaques Level 60, Governor Phillip Tower, 1 Farrer Place, SYDNEY, NSW | Failure of Gastric Lap Band |
| Mark Hodges, Solicitor & Attorney, Level 1, 154 Elizabeth St., Sydney NSW | Failure of Fibreglass Composite Water Lift Muffler |
| Meerkin & Apel Lawyers, 46 Caroline Street, South Yarra Vic 3141 | Recycling Process for Medical Waste |
| Middletons Lawyers, | Failure of Hair Cream tubes |

| | |
|--|--|
| Level 29, 200 Queen St, Melbourne VIC 3000 | |
| Middletons Lawyers, Level 29, 200 Queen St, Melbourne VIC 3000 | Failure of HDPE liner in Uranium SX plant |
| Minter Ellison Lawyers, GPO BOX 1272 Adelaide SA 5001 | Failure of ABS Water Filter Housing |
| Minter Ellison Lawyers Rialto Towers, 525 Collins Street., Melbourne VIC 3000 | Failure of Nitrile rubber tank liner |
| Moray & Agnew Solicitors, Level 8, 440 Collins Street, Melbourne VIC 3000 | Failure of Nitrile rubber tank liner |
| Trade Marks Attorney Norton Gledhill Commercial Lawyers, Level 23, 459 Collins Street Melbourne Vic 3000 | Composition of Polyurethane glove |
| Peter Black & Associates Level 8 114 William Street, MELBOURNE VIC 3000 | Failure of HIPS Layer Pads |
| Phillips Fox, 120 Collins Street, Melbourne 3000 | Failure of Flexible PP Liner |
| Phillips Fox, 120 Collins Street, Melbourne 3000 | Failure of Epoxy Phenolic Can Coating |
| Piper Alderman Lawyers, Level 24, 385 Bourke Street, Melbourne VIC 3000 | Cause of Defects in Blown Film |
| Piper Alderman Solicitors, Level 24, 385 Bourke Street, DX 30829 Collins Street Melbourne | Defects in Rotomolded Polyethylene Water Tanks |
| Phillips Ormonde Fitzpatrick, 367 Collins St., Melbourne 3000 | Failure of Corian Tables |
| Trivett Keating Solicitors, PO Box 678, Wodonga VIC 3689 | Failure of EPDM tank liner |
| NSG Expert Opinion Services, Rupert Myers Building, Gate 14, Barker Street, UNSW, SYDNEY, 2052 | Failure of Recycled Plastic Irrigation Pipe |
| Expert Opinion Services , A division of New South Global Pty Limited, Rupert Myers Building UNSW NSW 2052 DX 957 SYDNEY | Failure of PVC/nitrile solar heating collectors |
| NSG Expert Opinion Services, Rupert | Failure of Polyethylene-aluminium foil |

| | |
|---|--|
| Myers Building, Gate 14, Barker Street, UNSW, SYDNEY, 2052 | roofing insulation |
| UNISEARCH LIMITED, Rupert Myers Building, Gate 14, Barker Street, UNSW, SYDNEY, 2052 | Failure of Rubber Automotive Tyre |
| Wotton Kearney, Level 13 28 O'Connell Street, DX 10465, Sydney NSW 2000 | Failure analysis of polycarbonate water bottles |